

Date: 7/31/15

PCN No.: 326

PRODUCT CHANGE NOTICE

Dear Valued Lantronix Customer,

This is to inform you that a change will be made to the following products.

Change Type

Device Firmware

Products Affected

Part Number	Description	Old Revision	New Revision
SLC00812N-G3	8-Port, Single AC Power Supply, Secure Console Manager, ROHS, TAA	B17	C17
SLC00822N-G3	8-Port, Dual AC Power Supply, Secure Console Manager, ROHS, TAA	C24	D24
SLC00824N-G3	8-Port, Dual DC Power Supply, Secure Console Manager, ROHS, TAA	B17	C17
SLC01612N-G3	16-Port, Single AC Power Supply, Secure Console Manager, ROHS, TAA	C23	D23
SLC01622N-G3	16-Port, Dual AC Power Supply, Secure Console Manager, ROHS, TAA	C24	D24
SLC01624N-G3	16-Port, Dual DC Power Supply, Secure Console Manager, ROHS, TAA	B17	C17
SLC03212N-G3	32-Port, Single AC Power Supply, Secure Console Manager, ROHS, TAA	C20	D20
SLC03222N-G3	32-Port, Dual AC Power Supply, Secure Console Manager, ROHS, TAA	C24	D24
SLC03224N-G3	32-Port, Dual DC Power Supply, Secure Console Manager, ROHS, TAA	B17	C17
SLC04812N-G3	48-Port, Single AC Power Supply, Secure Console Manager, ROHS, TAA	C23	D23
SLC04822N-G3	48-Port, Dual AC Power Supply, Secure Console Manager, ROHS, TAA	D25	E25
SLC04824N-G3	48-Port, Dual DC Power Supply, Secure Console Manager, ROHS, TAA	B17	C17

Description and Extent of Change

Lantronix is pleased to announce the release of new and improved SLC firmware 6.2.0.0. The release includes new features and bug fixes including:

- Added option to disable web server via CLI
- Fixed SSL v3.0 POODLE vulnerability
- Fixed kernel lockups while running traffic over Ethernet port
- Upgraded OpenSSH
- Removed insecure RC4 cipher from web server

For customers that would like to take advantage of the above new capabilities, firmware is now available for download from our website: <http://www.lantronix.com/support/downloads>.

Effect of Change on Fit, Form, Function, Quality, or Reliability

Change is limited to product functionality.



7535 Irvine Center Dr.
Irvine | CA 92618 | USA
Tel: 949-453-3990
Fax: 949-453-3995
www.lantronix.com

Effective Date of Change

Affected products with firmware 6.2.0.0 will begin shipping from the factory on August 10, 2015.

If you have any questions, please contact your sales representative or Lantronix Customer Support at (866) 649-0721 or (949) 453-3990 x342.

