

## PRODUCT CHANGE NOTICE

Dear Lantronix Customer,

The purpose of this communication is to inform you of the availability of new firmware release for WiPort embedded Wi-Fi device server module.

### **Change Type**

Software

### **Products Affected**

#### Orderable Part Numbers

Part Number	Description	Old Revision	New Revision
WP2001000G-02	WIPORT B/G, BULK PACK	M16	N16
WP2002000G-02	WIPORT B/G AES, BULK PACK	G15	H15
WP2003000G-02	WIPORT B/G, JAPAN, BULK PACK	F13	G13
WP2006000G-02	WIPORT B/G AES, JAPAN, BULK PACK	F13	G13
WP200200SG-02	WIPORT B/G AES, SAMPLE	M17	N17
WP200600SG-02	WIPORT B/G AES JAPAN, SAMPLE	F14	G14

### **Description and Extent of Change**

Lantronix is pleased to announce the availability of new firmware release **6.8.0.9** for WiPort embedded Wi-Fi device server. The section below describes key highlights of the release.

Key highlights of 6.8.0.9 release are:

- BZ#33053 – Device drops Wi-Fi connection and does not reconnect without a power cycle. This issue only applies to specific APs and their configuration and is not generally observed. It was introduced when the updates to the KRACK vulnerability were released in 6.8.0.6 (previous release).

Refer to the release notes for a complete list of additional features and bug fixes.

### **Effect of Change on Fit, Form, Function, Quality, or Reliability**

Functional changes as noted above.

For customers that would like to take advantage of the new capabilities immediately, the new firmware, associated release notes and upgrade instructions are available for download from our website, <http://www.lantronix.com/support/downloads>.

**Effective Date of Change**

Affected products will begin shipping with the new software from Lantronix starting July 22, 2019.

If you have any questions, please contact your sales representative or Lantronix Technical Support at (800) 422-7044 or (949) 453-7198.