

PRODUCT CHANGE NOTICE

Dear Valued Lantronix Customer,

The purpose of this communication is to inform you of an upcoming change to the following product. This change is part of our effort and commitment to continuous improvement of our products and processes.

Change Type

Software

Product Affected

Part Number	Description	Old Revision	New Revision
A5135H	GNSS A5135H - SiRFstarV-based 52-channel GNSS receiver built-in patch antenna, -147 dBm acquisition sensitivity, -160 dBm navigation sensitivity, I ² C MEMS interface	A12	B12

Description and Extent of Change

Lantronix is pleased to announce the release of A5135H Firmware version 5.7.12-P3.5. This release includes new features and bug fixed including:

- Support MID 52 to output time associated with the current 1 PPS.
- Fix the negative clockBias.
- Fix MID67,1 output interval in 10Hz NAV mode
- Fix abnormal heading error and optimize estimated horizontal position error

For customers that would like to take advantage of the new capabilities immediately, the new firmware, associated release notes and upgrade instructions is available for download from our website, <http://www.lantronix.com/support/downloads>.

Effect of Change on Fit, Form, or Function

Functional changes as noted above.

Effective Date of Change

The change will go into effect for the listed products built from November 04, 2021 onwards.

If you have any questions, please contact your sales representative or Lantronix Technical Support at (800) 422-7044 or (949) 453-7198.