

PRODUCT CHANGE NOTICE

Dear Lantronix Customer,

The purpose of this communication is to inform you of an upcoming change to the following products. This change is part of our effort and commitment to continuous improvement of our products and processes.

Change Type

Software

Products Affected

Part Number	Description	Old Revision	New Revision
G526GP12S	INDSTRY PACK LTE CAT4 ROUTR,EMEA/APAC,LTE-3G-2G B28,20,8,3,1,7-B8,1-B8,3,10.8-60V DC, L GASP, DI, DI-O X2, VI-O X2, RS-232,RS-485,USB,WIFI 5,BT5 ETHRNT X2 GNSS,DUAL SIM,MICROSD SW EPACK INDUSTRIAL SUIT	A11	B11
G526GP17S	INDUSTRY PACK LTE CAT 4 ROUTER, JAPAN, SOUTH KOREA LTE B18,5(19),8,21,3(9),1,7,10.8-60V DC,L GASP,DI,DI-O X2,VI-O X2,RS-232,RS-485,USB,WIFI5,BT5,ETHRNT X2,GNSS,DUAL SIM,MICROSD SW EPACK INDUSTRIAL SUIT	A11	B11
G526GP1AS	INDUSTRY PK LTE CAT4 ROUTR,CAN/USA,LTE B71,12(17),13,14,26(5),66(10,4),25(2),10.8-60V DC,L GASP,DI,DI-O X2,VI-O X2,RS-232,RS-485,USB,WIFI5,BT5,ETHRNT X2;GNSS,DUAL SIM,MICROSD SW EPACK INDSTRIL SUIT	A11	B11
G526GP1AS1	INDUSTRY PACK LTE CAT 4 ROUTER FOR CANADA, USA; LTE B71,12(17),13,14,26(5),66(10,4),25(2); 10.8 - 60 V DC; L. GASP; DI; DI-O X2; VI-O X2; RS-232; USB; WI-FI 5; BT 5; ETHERNET X2; GNSS; DUAL SIM; MICROSD SW EPACK INDUSTRIAL SUIT	A11	B11
G526GP1ASG	INDSTRY PK LTE CAT4 ROUTR,CAN/USA,LTE B71,12(17),13,14,26(5),66(10,4),25(2),10.8-60V DC,L GASP,DI,DI-O X2,VI-O X2,RS-232,RS-485,USB,WIFI5,BT5,ETHRNT X2,GNSS,DUAL SIM,MICROSD SW EPACK INDSTRIL SUIT TAA	A12	B12
G526GP1CS	INDSTRY PK LTE CAT4 ROUTR,CHINA/THAI/INDNSA/INDIA,LTE3G-2G B5,8,3,1,40,41-B8,1-B8,3,10.8 60V DC,L GASP,DI,DI-O X2,VI-O X2,RS-232,RS-485,USB,WIFI5,BT5,ETHRNT X2,GNSS,DUAL SIM,MICROSD SW EPACK INDSTRY	A11	B11

Description and Extent of Change

Lantronix is pleased to announce the release of new and improved G526 series firmware version 2.0.0.0R28. The release includes new features and bug fixes including:

NEW FEATURES:

- Improves Home page and Status/Overview loading time for quick access to device.
- Improves last gasp handling and device shutdown after main power is unavailable.
- Add support for custom APN when connecting to the cellular network.
- Add support for updating the cellular module firmware.
- Copper Test diagnostic feature to test whether a port can link up or not through a RJ45 connector and determine the cable performance.

ConsoleFlow:

- Select On-Premise or Cloud server.
- Retrieve device syslog.
- Send CLI commands to device.
- Disable remote access from device and ConsoleFlow.
- Configure SSL Credentials and GPS.

Bug fixes:

- Improves firmware image verification before install.
- Fix a possible case where the device CPU usage became high.
- Stability and performance improvements.

Refer to the release notes for a complete list of features and bug fixes.

For customers that would like to take advantage of the new capabilities of firmware version 2.0.0.0R28, the new firmware available for download from our website: <http://www.lantronix.com/support/downloads>.

Reason for Change

New Firmware release

Effect of Change on Fit, Form, Function

Functional changes as noted on release notes.

Effective Date of Change

This change will go into effect for the listed products built from **January 2, 2023** onwards.

If you have any questions, please contact your sales representative or contact Lantronix Technical Support by submitting a ticket to: <https://ltrxdev.atlassian.net/wiki/spaces/LTRXTS/overview>