

## PRODUCT CHANGE NOTICE

Dear Lantronix Customer,

The purpose of this communication is to inform you of an upcoming change to the following products. This change is part of our effort and commitment to continuous improvement of our products and processes.

### **Change Type**

Firmware

### **Products Affected**

| Part Number | Description  | Old Revision | New Revision |
|-------------|--|--------------|--------------|
| F43H207S    | FOX4, JAPAN, LTE M & NB2 BANDS 1, 2, 3, 4, 5, 8, 12, 13, 18, 19, 20, 25, 26, 28, 66, 71, 85, GNSS, WIFI 4, BLE 4.2, ACC., INT. & EXT. ANT., MINI SIM, RS232, 3 I/O, I2C, RTC, 1 WIRE, BAT-01   | B11          | C11          |
| F43H102S    | FOX4, EMEA, LTE M & NB2 BANDS 1, 2, 3, 4, 5, 8, 12, 13, 18, 19, 20, 25, 26, 28, 66, 85, 2G FB, GNSS, WIFI 4, BLE 4.2, ACC., INT. & EXT. ANT., MINI SIM, RS232, 3 I/O, I2C, RTC, 1 WIRE, BAT-01 | B11          | C11          |
| F43H20FS    | FOX4, WW, LTE M & NB2 BANDS 1, 2, 3, 4, 5, 8, 12, 13, 18, 19, 20, 25, 26, 28, 66, 71, 85, GNSS, WIFI 4, BLE 4.2, ACC., INT. & EXT. ANT., MINI SIM, RS232, 3 I/O, I2C, RTC, 1 WIRE, BAT-01      | B11          | C11          |
| F43H507S    | FOX4, JAPAN, LTE M & NB2 BANDS 1, 2, 3, 4, 5, 8, 12, 13, 18, 19, 20, 25, 26, 28, 66, 71, 85, GNSS, WIFI 4, BLE 4.2, ACC., INT. & EXT. ANT., MINI SIM, RS485, 3 I/O, I2C, RTC, 1 WIRE, BAT-01   | A11          | B11          |
| F43H50FS    | FOX4, WW, LTE M & NB2 BANDS 1, 2, 3, 4, 5, 8, 12, 13, 18, 19, 20, 25, 26, 28, 66, 71, 85, WIFI 4, BLE 4.2, GNSS, ACC., INT. & EXT. ANT., MINI SIM, RS485, 3 I/O, I2C, RTC, 1 WIRE, BAT-01      | A11          | B11          |
| F44H102S    | FOX4, EMEA, LTE CAT 1 BANDS 1, 3, 7, 8, 20, 28, 3G 1 & 8, 2G 3 & 8, GNSS, ACC., WIFI 4, BLE 4.2, INT. & EXT. ANT., MINI SIM, RS232, 3 I/O, I2C, RTC, 1 WIRE, BAT-01                            | B11          | C12          |

### **Description and Extent of Change**

Lantronix is pleased to announce the release of new and improved FOX4 firmware version 4.2.0\_rc25. The release includes bug fixes including:

Bug fixes:

- Fixes for better DNS handling.
- Fixes memory leak in the WIFI driver.

For customers that would like to take advantage of the new capabilities of firmware version 4.2.0\_rc25, the new firmware available for download from our website: <http://www.lantronix.com/support/downloads>.

**Reason for Change**

New firmware released for production.

**Effect of Change on Fit, Form, Function**

Functional changes as noted on release notes.

**Effective Date of Change**

This change will go into effect for the listed products built from **January 2<sup>nd</sup>, 2024** onwards.

If you have any questions, please contact your sales representative or contact Lantronix Technical Support by submitting a ticket to: <https://ltxdev.atlassian.net/wiki/spaces/LTRXTS/overview>