



SISPM1040-382-LRT Release Notes

Date: February 17, 2016

Kernel:2.50

Version: 1.23

Overview

This release note covers the requirements, important notes, new features and changes, addressed issues and known limitations for the SISPM1040-382-LRT product.

Requirements:

Firmware version v1.23 and these release notes apply to the following products:

- SISPM1040-382-LRT

Bug Fixes:

- Browsers that block Poodles SSL version 3.0 are unable to establish an HTTPS connection to manage the SISPM1040-382-LRT
- Running the McAfee IT Security Scan tool Foundstone ver. 7.5 on a SISPM1040-382-LRT causes the management interface to become unresponsive and requires a reboot to restore management access.
- Multicast is broadcasted to all ports, when IGMP snooping is enabled on the SISPM1040-382-LRT
- SISPM1040-382-LRT experiences a crash and reboot after enabling RADIUS using the Web UI