LANTRONIX

Date: 09/21/2026 PCN:1134

PRODUCT CHANGE NOTICE

Dear Valued Lantronix Customer,

The purpose of this communication is to inform you of an upcoming change to the following products. This change is part of our effort and commitment to continuous improvement of our products and processes.

Change Type

Software

Products Affected

Part Number	Description	Old Revision	New Revision
F43H102S	FOX4, EMEA, LTE M & NB2 BANDS 1, 2, 3, 4, 5, 8, 12, 13, 18, 19, 20, 25, 26, 28, 66, 85, 2G FB, GNSS, WIFI 4, BLE 4.2, ACC., INT. & EXT. ANT., MINI SIM, RS232, 3 I/O, I2C, RTC, 1 WIRE, BAT-01	F12	G12
F43H207S	fOX4, JAPAN, LTE M & NB2 BANDS 1, 2, 3, 4, 5, 8, 12, 13, 18, 19, 20, 25, 26, 28, 66, 71, 85, GNSS, WIFI 4, BLE 4.2, ACC., INT. & EXT. ANT., MINI SIM, RS232, 3 I/O, I2C, RTC, 1 WIRE, BAT-01	F12	G12
F43H20FS	FOX4, WW, LTE M & NB2 BANDS 1, 2, 3, 4, 5, 8, 12, 13, 18, 19, 20, 25, 26, 28, 66, 71, 85, GNSS, WIFI 4, BLE 4.2, ACC., INT. & EXT. ANT., MINI SIM, RS232, 3 I/O, I2C, RTC, 1 WIRE, BAT-01	F12	G12
F43H502S	FOX4, EMEA, LTE M & NB2 BANDS 1, 2, 3, 4, 5, 8, 12, 13, 18, 19, 20, 25, 26, 28, 66, 85, 2G FB, WIFI 4, BLE 4.2, GNSS, ACC., INT. & EXT. ANT., MINI SIM, RS485, 3 I/O, I2C, RTC, 1 WIRE, BAT-01	D11	E11
F43H507S	FOX4, JAPAN, LTE M & NB2 BANDS 1, 2, 3, 4, 5, 8, 12, 13, 18, 19, 20, 25, 26, 28, 66, 71, 85, GNSS, WIFI 4, BLE 4.2, ACC., INT. & EXT. ANT., MINI SIM, RS485, 3 I/O, I2C, RTC, 1 WIRE, BAT-01	E12	F12
F43H50FS	FOX4, WW, LTE M & NB2 BANDS 1, 2, 3, 4, 5, 8, 12, 13, 18, 19, 20, 25, 26, 28, 66, 71, 85, WIFI 4, BLE 4.2, GNSS, ACC., INT. & EXT. ANT., MINI SIM, RS485, 3 I/O, I2C, RTC, 1 WIRE, BAT-01	E12	F12
F43R202S	FOX4, EMEA, LTE M & NB2 BANDS 1, 2, 3, 4, 5, 8, 12, 13, 18, 19, 20, 25, 26, 28, 66, 85, 2G FB, DR GNSS, WIFI 4, BLE 4.2, ACC., INT. & EXT. ANT., MINI SIM, RS232, 3 I/O, I2C, RTC, 1 WIRE, BAT-01	C11	D11
F43R20FS	FOX4, WW, LTE M & NB2 BANDS 1, 2, 3, 4, 5, 8, 12, 13, 18, 19, 20, 25, 26, 28, 66, 71, 85, DR GNSS, WIFI 4, BLE 4.2, ACC., INT. & EXT. ANT., MINI SIM, RS232, 3 I/O, I2C, RTC, 1 WIRE, BAT-01	C11	D11
F44H102S	FOX4, EMEA, LTE CAT 1 BANDS 1, 3, 7, 8, 20, 28, 3G 1& 8, 2G 3 & 8, GNSS, ACC., WIFI 4, BLE 4.2, INT. & EXT. ANT., MINI SIM, RS232, 3 I/O, I2C, RTC, 1 WIRE, BAT-01	F13	G13
F44H502S	FOX4, EMEA, LTE CAT 1 BANDS 1, 3, 7, 8, 20, 28, 3G 1& 8, 2G 3 & 8, GNSS, WIFI 4, BLE 4.2, ACC., INT. & EXT. ANT., MINI SIM, RS485, 3 I/O, I2C, RTC, 1 WIRE, BAT-01	D11	E11

Description and Extent of Change

Lantronix is pleased to announce the release of new and improved firmware v4.7.0_rc6 for fox4. The release includes new bug fixes including:

Bugs fix:

- Fix for DNS/lookup issues with race condition between WiFi and PPP

For customers that would like to take advantage of the new capabilities of firmware version v4.7.0_rc6, the new firmware available for download from our website: http://www.lantronix.com/support/downloads.

Reason for Change

New firmware v4.7.0_rc6

Effect of Change on Fit, Form, or Function

There will be no fit, form or function change.

Effective Date of Change

Example: Affected products with firmware version v4.7.0_rc6 will begin shipping from the factory by Sept 22th, 2026

If you have any questions, please contact your sales representative or contact Lantronix Technical Support by submitting a ticket to: https://ltrxdev.atlassian.net/wiki/spaces/LTRXTS/overview