Date: 11/02/2026 PCN: 1153

PRODUCT CHANGE NOTICE

Dear Lantronix Customer,

The purpose of this communication is to inform you of an upcoming change to the following product. This change is part of our effort and commitment to continuous improvement of our products and processes.

Change Type

Software

Products Affected

Part Number	Description	Old Revision	New Revision
M114B00FS	MODEM M114 - LTE CAT. 1 BIS - RS-232 & USB PORTS - 2 I/OS - MPACK	C14	D14

Description and Extent of Change

Lantronix is pleased to announce the release of new and improved M114 firmware version v3.2.0.0R4. The release includes bug fixes including:

Bug fixes:

- Issue where RS-232 communication failed.
- issue where the device rebooted when MAX_AT_ERROR_COUNT exceeded 15.
- issue where the device did not respond to TCPTERM.
- issue where the device became unresponsive after the second trigger.

For customers that would like to take advantage of the new capabilities of firmware version v3.2.0.0R4, the new firmware available for download from our website: http://www.lantronix.com/support/downloads.

Reason for Change

New Firmware release

Effect of Change on Fit, Form, Function

Functional changes as noted on release notes.

Effective Date of Change

This change will go into effect for the listed products built from Nov 10th , 2026 onwards.

If you have any questions, please contact your sales representative or contact Lantronix Technical Support by submitting a ticket to: https://ltrxdev.atlassian.net/wiki/spaces/LTRXTS/overview