**IONPS-A & IONPS-D Release Notes**
**Date:  December 2, 2015**
**Version: 1.2.3**

**Overview**
This release note covers the requirements, important notes, new features and changes, addressed issues and known limitations for the power supply modules used in the ION 19-slot chassis.

**Requirements:**
Firmware version 1.2.3 and these release notes apply to the following products:
- • IONPS-A      ION AC power supply module for the 19-slot chassis
- • IONPS-D      ION DC power supply module for the 19-slot chassis

**New Features and Enhancements:**
The following is a list of new features and enhancements in version 1.2.3 of the IONPS-A and IONPS-D.
- • During a complete loss of power of one power supply module in a dual powered chassis, threshold traps (temp, voltage, power, fan) will now be set and the activation of the Dry Contact Relay modules will now occur with the upgrade to the 1.2.3 firmware

**Related Documentation:**
- • ION219-x User Guide (33412)
- • IONPS-A User Guide (33423)
- • IONPS-D User Guide (33424)