



Date: 10/05/2026

PCN-1138

## PRODUCT CHANGE NOTICE

Dear Lantronix Customer,

The purpose of this communication is to inform you of an upcoming change to the following products. This change is part of our effort and commitment to continuous improvement of our products and processes.

### **Change Type**

Firmware

### **Products Affected**

| Part Number | Description                                                                                                                                                                                              | Old Revision | New Revision |
|-------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------|--------------|
| EDS5008     | EDS 5000 Series Device Server. 8 port device server, with 10/100/1000 RJ-45 / 100/1000 SFP Combo Ethernet port., 100-240 VAC & 24/48 VDC inputs, 1RU rackmount unit. Contains North American power cord. | C12          | D12          |
| EDS5016     | EDS 5000 Series Device Server. 16 port device server, with 10/100/1000 RJ-45 / 100/1000 SFP Combo Ethernet port., 100-240 VAC & 24/48 VDC inputs, 1RU rackmount unit. Contains North American power cord | C12          | D12          |
| EDS5032     | EDS 5000 Series Device Server. 32 port device server, with 10/100/1000 RJ-45 / 100/1000 SFP Combo Ethernet port., 100-240 VAC & 24/48 VDC inputs, 1RU rackmount unit. Contains North American power cord | C12          | D12          |

### **Description and Extent of Change**

Lantronix is pleased to announce the release of new and improved EDS5000 series firmware version 2.4.0.0R1. The release includes bug fixes including:

#### **BUG FIXES:**

- Fix for firmware upgrade fails from perception

Refer to the release notes for a complete list of features and bug fixes.

For customers that would like to take advantage of the new capabilities of firmware version 2.4.0.0R1, the new firmware available for download from our website: <http://www.lantronix.com/support/downloads>.

### **Reason for Change**

Releasing of new firmware

### **Effect of Change on Fit, Form, Function**

There is no impact to product fit, form, and function

#### **Note:**

This firmware is compatible for hardware revision B11 or later.

### **Effective Date of Change**

This change will go into effect for the listed products built from **October 9<sup>th</sup>, 2026** onwards.

If you have any questions, please contact your sales representative or contact Lantronix Technical Support by submitting a ticket to: <https://ltrxdev.atlassian.net/wiki/spaces/LTRXTS/overview>