Carrier Ethernet Release Notes
Date: September 4, 2014
Version: 1.7.4.16

Overview
This release note covers the requirements, important notes, new features and changes, addressed issues and known limitations for the S3280, S3280-TST, S4140, S4212 and S4224 product families.

Management of these products is available using Converge™ EMS, SNMP, Web or Command Line Interface (CLI) locally or via Telnet.

Requirements:
Firmware version 1.7.4.16 and these release notes apply to the following products:
- S3280
- S3280-TST
- S4140
- S4212
- S4224

New Features and Enhancements:
The following is a list of new features and enhancements for version 1.7.4.16
- Syslog messages to indicate when a user attempts to log in via CLI, Web or console
- Syslog messages on add/remove of authorized users

Fixes in 1.7.4.16
- Fix for issues with SSH and TACACS+ where session exits were handled incorrectly

Known Feature Limitations:
The following is a list of currently known issues for the S3280.
- MEPs do not work over ports using link aggregation
- L2CP settings are in the CLI only and not Web interface

Related Documentation:
Please visit the specific product web page for detailed documentation
- Install Guide
- User Guide
- CLI Reference Guide

MIBs:
- TNMIBs_1.7.4.16.zip file