



15353 Barranca Parkway
Irvine | CA 92618 | USA
Tel: 949-453-3990
Fax: 949-453-7170
www.lantronix.com

July 22, 2004

PCN No.: PCN-014

Product Change Notice

Dear Valued Lantronix Customer,

The purpose of this document is to notify you of a firmware change to the SCS820B, SCS1620B, SCS3205 and SCS4805 Secure Console Servers.

Beginning in July 2004, firmware version 4.4 will ship on the following products:

<u>Model Number</u>	<u>Part Number</u>
SCS820B (AC)	500.000.0820B
SCS820B (DC)	500.048.0820B
SCS1620B (AC)	500.000.1620B
SCS1620B (DC)	500.048.1620B
SCS3205	SCS3205U-01
SCS4805	SCS4805U-01

This version replaces the previous version, v4.3. Version 4.4 firmware adds an update to the SSH implementation to address new security alerts. In addition, v4.4 also includes fixes for known issues in v4.3.

For more information, please refer to detailed release notes available at the following location: <ftp://ftp.lantronix.com/pub/> or contact Lantronix Customer Support at (866) 649-0721 or (949) 453-3990 x342.

LANTRONIX[®]
Product Marketing