



15353 Barranca Parkway
Irvine | CA 92618 | USA
Tel: 949-453-3990
Fax: 949-453-7170
www.lantronix.com

January 31, 2005

PCN No.: PCN-023

Product Change Notice

Dear Valued Lantronix Customer,

The purpose of this document is to notify you of a firmware change to the USB ServerSwitch.

Beginning in March 2005, firmware version 1.54 will ship on the following products:

<u>Part Number</u>	<u>Description</u>
300.000.1000B	USB ServerSwitch for Sun, SGI and PCs 8 port, 2 user

Version 1.54 includes the following new features:

- **USB Hub Support:** USB hubs are now supported on User ports, allowing the use of active USB extenders (which have internal USB hubs).
- **OSD Timeout:** The On Screen Display (OSD) will now timeout and return to present host if there is no activity for 60 seconds.
- **Improved Scroll Lock key handling:** A Scroll Lock key will not be sent out to the host until a 1/2 second timeout is met or another key is pressed.

For more information, please refer to detailed release notes available at the following location: ftp://ftp.lantronix.com/pub/usb_serverswitch/1.54/ or contact Lantronix Customer Support at (866) 649-0721 or (949) 453-3990 x342.

LANTRONIX[®]
Product Marketing