



Date: 09/25/2025

PCN: 1044

PRODUCT CHANGE NOTICE

Dear Lantronix Customer,

The purpose of this communication is to inform you of an upcoming change to the following products. This change is part of our effort and commitment to continuous improvement of our products and processes.

Change Type

Software

Products Affected

Part Number	Description	Old Revision	New Revision
F33H002B01	TRACKER FOX3-4G-M1-FB-WW-4G CATM1/NB1 BANDS 2, 3, 4, 5, 8, 12, 13, 20-2G FB-GNSS-ACCELEROMETER, INT/EXT ANT-MINI SIM-2 X RS232-3 I/O-I2C-RTC-1 WIRE-MINI USB-AVL SOFTWARE BAT-01 1000 MAH LI-ION BATTERY	G12	H12
F33H002B02	FOX3-4G-M1/2G-PROMOTION-KIT	F13	G13
F33H002S	FOX3 4G M1 FB - Worldwide - 4G CatM1/NB1 Bands 2, 3, 4, 5, 8, 12, 13, 20 -2G FB - GNSS - Accelerometer, int & ext ant - Mini Sim - 2 X RS232 - 3 I/O - I2C - RTC - 1 Wire - Mini USB - AVL Software	G12	H12
F33H007S	TRACKER FOX3-4G-M1-WW-4G CATM1/NB1 BANDS JAPAN VERSION-GNSS-ACCELEROMETER, INT/EXT ANT-MINI SIM-2 X RS232-3 I/O-I2C-RTC-1 WIRE-MINI USB-AVL SOFTWARE BAT-01 1000 MAH LI-ION BATTERY	D13	E13
F33H502S	TRACKER FOX3-4G-M1-FB-WW-4G CATM1/NB1 BANDS 2, 3, 4, 5, 8, 12, 13, 20-2G FB-GNSS-ACCELEROMETER, INT/EXT ANT-MINI SIM-2 X RS485-3 I/O-I2C-RTC-1 WIRE-MINI USB-AVL SOFTWARE BAT-01 1000 MAH LI-ION BATTER	C12	D12
F33HGZ2B01	TRACKER FOX3-M1-BLE-WORLDWIDE-LTE-M/NB2 BANDS 2, 3, 4, 5, 8, 12, 13, 20-2G FB-GNSS-ACCELEROMETER, INT/EXT ANT-BT LE 4.1-MINI SIM-2 X RS232-3 I/O-I2C-RTC-1 WIRE-MINI USB-AVL SOF-INCBAT-01 RECHARGEABLE	E14	F14
F33HGZ2S	FOX3 4G M1 FB BLE-WORLDWIDE-4G CATM1/NB1 BANDS 2, 3, 4, 5, 8, 12, 13, 20-2G FB-GNSS-ACCELEROMETER, INT/EXT ANT-BT LE 4.1 -MINI SIM - 2 X RS232 -3 I/O - I2C - RTC - 1 WIRE - MINI USB - AVL SOFTWARE	F14	G14

Description and Extent of Change

Lantronix is pleased to announce the release of new and improved Fox3 series firmware version 3.26.0_RC9. The release includes bug fixes including:

Bug fixes:

- Changed PercepXion watchdog enum for backward compatibility.
- CAN bus, PX, MQTT, TCP client improvements.
- PXMqtt: reconnect if subscribe fails.
- After FW upgrade complete GPSSTATE event shows error as cancel download.
- Intermittent-Sometimes connect to server failed is showing but next retry works.

For customers that would like to take advantage of the new capabilities of firmware version 3.26.0_RC9, the new firmware available for download from our website: <http://www.lantronix.com/support/downloads>.

Reason for Change

New Firmware

Effect of Change on Fit, Form, Function

Functional changes as noted on release notes.

Effective Date of Change

This change will go into effect for the listed products built from **October 2nd, 2025** onwards.

If you have any questions, please contact your sales representative or contact Lantronix Technical Support by submitting a ticket to: <https://ltrxdev.atlassian.net/wiki/spaces/LTRXTS/overview>