

PRODUCT CHANGE NOTICE

Dear Valued Lantronix Customer,

This is to inform you that a change will be made to the following products.

Change Type

Software

Products Affected

Part Number	Description	Old Revision	New Revision
SLB882KIT-15P	SLB882 Branch Office Manager, 110VAC output, NEMA 5-15P (15A) Power Cords Included	H20	J20
SLB882KIT-20P	SLB882 Branch Office Manager, 110VAC output, NEMA 5-20P (20A) Power Cords Included	H20	J20
SLB8824KIT-AP	SLB8824 Branch Office Manager, 220VAC output, AU and CN Power Cords Included	F17	G17
SLB8824KIT-EU	SLB8824 Branch Office Manager, 220VAC output, EU and UK Power Cords Included	F17	G17
SLB8824KIT-WW	SLB8824 Branch Office Manager, 220VAC output, 1xEU, 1xUK, 1xAU, 1xCN Power Cords Included	F17	G17
SLB882KIT-15P-G	SLB882 Branch Office Manager, 110VAC output, NEMA 5-15P (15A) Power Cords Included TAA	A11	B11
SLB882KIT-20P-G	SLB882 Branch Office Manager, 110VAC output, NEMA 5-20P (20A) Power Cords Included TAA	A11	B11

Lantronix is pleased to announce the release of new and improved SLB firmware 7.0.0.0RC7.

Description and Extent of Change

The release includes new features and bug fixes including:

- ConsoleFlow System Log and Configuration File
- Support has been added in ConsoleFlow for saving system logs and configuration files from the SLB.
- Unique Default Sysadmin Password.
- For newly manufactured units, the default sysadmin password will be unique for each SLB.

- The default sysadmin password will be the last 8 characters of the Device ID if it is set, or the last 8 characters of the serial number if the Device ID is not set.
- This feature will not be present on units that are updated via a patch firmware update.

Reason for Change

New features and expanded capabilities

For SLB customers who would like to take advantage of the above new capabilities, the firmware and associated release notes are now available for download from our website:

<https://www.lantronix.com/products/lantronix-slb/#docs-downloads>

More information about SLB Branch Office Manager is available on our website:

<https://www.lantronix.com/products/lantronix-slb>

Effect of Change on Fit, Form, or Function

Functional changes only as noted above.

If you have any questions, please contact your sales representative or Lantronix Technical Support at (800) 422-7044 or (949) 453-7198.