

PRODUCT CHANGE NOTICE

Dear Lantronix Customer,

The purpose of this communication is to inform you of the availability of new software release for E-Series Router Products.

Change Type

Software

Products Affected

Part Number	Description	Old Revision	New Revision
E213F002S	ROUTER, E213 WORDLWIDE, LTE-M1/NB-IOT, 2G FB, 2 ETHERNET, DUAL SIM, RS-232 PORT, WI-FI, SD CARD, 2 I/O EPACK	A12	B12
E213G002S	ROUTER E213 WORDLWIDE - LTE-M1 / NB-IOT - 2G FB - 2 ETHERNET, DUAL SIM, RS-232 PORT, WI-FI, SD CARD, 2 I/O - EPACK	A12	B12
E213G00FS	ROUTER E213 WORDLWIDE - LTE-M1 / NB-IOT - 2 ETHERNET, DUAL SIM, RS-232 PORT, WI-FI, SD CARD, 2 I/O - EPACK	A12	B12
E214F00CB26	E214F00CS ROUTER WITH ANTENNA A32M0, CABLE KEECO, POWER CABLE KDC42, DIN CLIPBR551 (HSN CODE: 85176930)	A12	B12
E215F002B27	E215F002S ROUTER WITH ANTENNA A17C1, CABLE KEECO, POWER CABLE KDC42, DIN CLIPBR551 (HSN CODE: 85176930)	A12	B12
E218F004S	ROUTER E218 BRAZIL ANZ THAILAND MALAYSIA SINGAPORE - LTE CAT4 BAND 28, 5, 8, 3,1 - 3G FB1, 5, 8 -2G FB 8, 3 - 2 ETHERNET, DUAL SIM, RS-232 PORT, WI-FI, SD CARD, 2 I/O - EPACK	A12	B12
E218F005S	ROUTER E218 DOCOMO - JAPAN - LTE CAT4 BAND 19, 21, 1 - 2 ETHERNET, DUAL SIM, RS-232 PORT, WI-FI, SD CARD, 2 I/O - EPACK	A12	B12
E218F009S	ROUTER E218 LG U+ - LTE CAT4 BAND 5, 3, 1, 7 - 2 ETHERNET, DUAL SIM, RS-232 PORT, WI-FI, SD CARD, 2 I/O - EPACK	A12	B12
E218G004S	ROUTER, E218, LTE CAT4 BAND, ETHERNET, DUAL SIM, RS-232 PORT, Wi-Fi, SD CARD, 2 I/O EPACK, BANZ, GNSS	02P	A11
E225FLZ2B25	E225FLZ2S ROUTER WITH ANTENNA A17C1, CABLE KEECO, POWER CABLE KDC22, DIN CLIP BR351 (HSN CODE: 85176930)	A12	B12

E225HPLFB25	E225HPLFS ROUTER WITH ANTENNA A17C1, CABLE KEECO, POWER CABLE KDC22, DIN CLIP BR351 (HSN CODE: 85176930)	A12	B12
E225HPLFS	ROUTER E225 WORLDWIDE - 3G BAND 1, 2, 5, 8 - 2G FB BAND 2, 3, 5, 8 - 2 ETHERNET, RS485, PDPOE, WIFI, LAST GAST, 2 I/O, EXT TEMP, GNSS, EPACK	A12	B12
E228G002S	ROUTER E228 EMEA - LTE CAT4 BAND 1, 3, 7, 8, 20, 28 - 3G FB BAND 1,8 - 2G FB BAND 3, 8 - 2 ETHERNET, RS485, WIFI, EXTENDED LAST GAST, 2 I/O EXT TEMP, GPSONE, EPACK	A12	B12
E228G004S	ROUTER E228 ASIA PACIFIC - LTE CAT4 BAND 1, 3, 5, 7, 8, 28 - 3G FB BAND 1, 5, 8 - 2G FB BAND 3, 8 - 2 ETHERNET RS485, WIFI, LAST GAST, 2 I/O EXT TEMP, GPSONE, EPACK	A12	B12
E228G00CB28	E228G00CS ROUTER WITH ANTENNA A32M0, CABLE KEECO, POWER CABLE KDC22, DIN CLIP BR351 (HSN CODE: 85176930)	A12	B12
E228G00CS	ROUTER E228 CHINA INDIA - LTE CAT4 BAND 1, 3, 5 TDD 40, 41- 3G FB BAND 1, 8 - 2G FB 3, 8 - 2 ETHERNET RS485, WIFI, EXTENDED LAST GAST, 2 I/O EXT TEMP, GPSONE, EPACK	A12	B12
E228HPL3S	ROUTER E228 ASIA PACIFIC - LTE CAT4 BAND 3, 7, 28 - 2 ETHERNET RS485, PDPOE, WIFI, LAST GAST, 2 I/O EXT TEMP, GNSS, EPACK	A12	B12
E228HPL9S	ROUTER E228 SOUTH KOREA - LTE CAT4 BAND 1, 3, 5, 7 - 2 ETHERNET RS485, PDPOE, WIFI, LAST GAST, 2 I/O EXT TEMP, GNSS, EPACK	A12	B12

Description and Extent of Change

Lantronix is pleased to announce the availability of new firmware release **v2.4.5.0** for E-Series Router Products.

Refer to the release notes for a complete list of features and bug fixes.

Effect of Change on Fit, Form, Function, Quality, or Reliability

Functional changes as noted on release notes.

For customers that would like to take advantage of the new capabilities immediately, the new firmware, associated release notes and upgrade instructions are available for download from our website, <http://www.lantronix.com/support/downloads>.

Effective Date of Change

This change will go into effect for the listed products built from **August 4, 2020** onwards.

If you have any questions, please contact your sales representative or Lantronix Technical Support at (800) 422-7044 or (949) 453-7198.