

PRODUCT CHANGE NOTICE

Dear Valued Lantronix Customer,

This is to inform you that a change will be made to the following products.

Change Type

Software

Products Affected

Part Number	Description	Old Revision	New Revision
SLB882KIT-15P	SLB882 Branch Office Manager, 110VAC output, NEMA 5-15P (15A) Power Cords Included	J20	K20
SLB882KIT-20P	SLB882 Branch Office Manager, 110VAC output, NEMA 5-20P (20A) Power Cords Included	J20	K20
SLB8824KIT-AP	SLB8824 Branch Office Manager, 220VAC output, AU and CN Power Cords Included	G17	H17
SLB8824KIT-EU	SLB8824 Branch Office Manager, 220VAC output, EU and UK Power Cords Included	G17	H17
SLB8824KIT-WW	SLB8824 Branch Office Manager, 220VAC output, 1xEU, 1xUK, 1xAU, 1xCN Power Cords Included	G17	H17
SLB882KIT-15P-G	SLB882 Branch Office Manager, 110VAC output, NEMA 5-15P (15A) Power Cords Included TAA	B11	C11
SLB882KIT-20P-G	SLB882 Branch Office Manager, 110VAC output, NEMA 5-20P (20A) Power Cords Included TAA	B11	C11

Description and Extent of Change

Lantronix is pleased to announce the release of new and improved SLB firmware 7.4.0.0R8.

Refer to the release notes for a complete list of new features.

For SLB customers that would like to take advantage of the above new capabilities, the firmware and associated release notes are now available for download from our website:

<http://www.lantronix.com/products/lantronix-slb/#docs-downloads>

More information about SLB Branch Office Manager is available on our website:
<https://www.lantronix.com/products/lantronix-slb>

Effect of Change on Fit, Form, or Function

Functional changes only as noted above.

Effective Date of Change

This change will go into effect for the listed products built from November 30, 2020 onwards.

If you have any questions, please contact your sales representative or Lantronix Technical Support at (800) 422-7044 or (949) 453-7198.