

PRODUCT CHANGE NOTICE

Dear Lantronix Customer,

The purpose of this communication is to inform you of the availability of new software release for M-Series Modem Products.

Change Type

Software

Products Affected

Part Number	Description	Old Revision	New Revision
M114F000S	MODEM M114 AT&T, TMOBILE, SPRINT - NORTH AMERICA - LTE CAT. 1 BAND 12, 5, 4, 2 - 3G FB BAND 5, 2 - RS-232 & USB PORTS - 2 I/OS - MPACK	A12	B12
M114F001S	MODEM M114 US / VERIZON - LTE CAT. 1 BAND 13/4 - NO FALL BACK - RS-232 & USB PORTS - 2 I/OS	A12	B12
M114F002B23	M114F002S MODEM WITH ANTENNA A32M0, CABLE KS990, POWER CABLE KDC42, DIN CLIP BR350 (HSN CODE: 85176230)	A12	B12
M114F002S	MODEM M114 EMEA - LTE CAT. 1 BAND 20, 3, 7 - 2G FB BAND 8, 3 - RS-232 & USB PORTS - 2 I/OS - MPACK	A12	B12
M114F003B23	M114F003S MODEM WITH ANTENNA A32M0, CABLE KS990, POWER CABLE KDC42, DIN CLIP BR350 (HSN CODE: 85176230)	A12	B12
M114F003S	MODEM M114 ASIA PACIFIC - LTE CAT. 1 BAND 28, 8, 3 - 3G FB BAND 1 - RS-232 & USB PORTS - 2 I/OS - MPACK	A12	B12
M114F005S	MODEM M114 DOCOMO - JAPAN - LTE CAT. 1 BAND 19, 1 - NO FALL BACK - RS-232 & USB PORTS - 2 I/OS - MPACK	A12	B12
M114F003FB1MOP	M114F003S MODEM FITTED INSIDE FUJITEC'S RMS BOX (SINGAPORE VARIANT WITH A RELAY SUBSTITUTED FOR THE STANDARD TERMINAL BLOCK, 100.8 MM-TALL COVER, NO SIM) - PROTOTYPE	A12	B12

Description and Extent of Change

Lantronix is pleased to announce the availability of new firmware release **v2.7.0.0** for M-Series Modem Products.

Refer to the release notes for a complete list of features and bug fixes.

Effect of Change on Fit, Form, Function, Quality, or Reliability

Functional changes as noted on release notes.

For customers that would like to take advantage of the new capabilities immediately, the new firmware, associated release notes and upgrade instructions are available for download from our website, <http://www.lantronix.com/support/downloads>.

Effective Date of Change

This change will go into effect for the listed products built from **January 1, 2021** onwards.

If you have any questions, please contact your sales representative or Lantronix Technical Support at (800) 422-7044 or (949) 453-7198.