

PRODUCT CHANGE NOTICE

Dear Lantronix Customer,

The purpose of this communication is to inform you of the availability of new software release for Bolero40 Series Products.

Change Type

Software

Products Affected

Part Number	Description	Old Revision	New Revision
B41H00FB02	BOLERO41-PROMOTION-KIT	A11	B11
B41H00FS	BOLERO41, 60189, WORLWIDE - 2G BAND 5/8/3/2 - IP 68 ? GNSS - LI.ION BATTERY BACKUP - RS232 2 WIRES - 2 I/O - 1 WIRE INTERFACE - AVL SOFTWARE	A12	B12
B45H00FB02	BOLERO45-PROMOTION-KIT	A11	B11
B45H00FS	BOLERO45, 60190, Worlwide - 3G band 5/8/2/1 - 2G FB - IP 68 ? GNSS - Li.Ion battery backup - RS232 2 wires - 2 I/O - 1 Wire interface - AVL Software	A11	B11

Description and Extent of Change

Lantronix is pleased to announce the availability of new firmware release **v3.12.0RC2** for Bolero40 Series Products.

Refer to the release notes for a complete list of features and bug fixes.

Effect of Change on Fit, Form, Function, Quality, or Reliability

Functional changes as noted on release notes.

For customers that would like to take advantage of the new capabilities immediately, the new firmware, associated release notes and upgrade instructions are available for download from our website, <http://www.lantronix.com/support/downloads>.

Effective Date of Change

This change will go into effect for the listed products built from **January 1, 2021** onwards.

If you have any questions, please contact your sales representative or Lantronix Technical Support at (800) 422-7044 or (949) 453-7198.