

PRODUCT CHANGE NOTICE

Dear Lantronix Customer,

The purpose of this communication is to inform you of the availability of new software release for M-Series M113 Modem Products.

Change Type

Software

Products Affected

Part Number	Description	Old Revision	New Revision
M113F002S	MODEM M113M1/NB1 2GFB WORLDWIDE - LTE-M1 / NB-IOT BAND 12, 28, 13, 20, 26, 8, 3, 4, 25, 1 - 2G FB, RS-232 & USB PORTS - 2 I/OS - MPACK	A12	B12
M113F00FS	MODEM M113M1/NB1 WORLDWIDE - LTE-M1 / NB-IOT BAND 12, 28, 13, 20, 26, 8, 3, 4, 25, 1 - RS-232 & USB PORTS - 2 I/OS - MPACK	A12	B12

Description and Extent of Change

Lantronix is pleased to announce the availability of new firmware release **v2.2.0.0** for M-Series M113 Modem Products.

Refer to the release notes for a complete list of features and bug fixes.

Effect of Change on Fit, Form, Function, Quality, or Reliability

Functional changes as noted on release notes.

For customers that would like to take advantage of the new capabilities immediately, the new firmware, associated release notes and upgrade instructions are available for download from our website, <http://www.lantronix.com/support/downloads>.

Effective Date of Change

This change will go into effect for the listed products built from **February 11, 2021** onwards.

If you have any questions, please contact your sales representative or Lantronix Technical Support at (800) 422-7044 or (949) 453-7198.