

PRODUCT CHANGE NOTICE

Dear Valued Lantronix Customer,

The purpose of this communication is to inform you of an upcoming change to the following product. This change is part of our effort and commitment to continuous improvement of our products and processes.

Change Type

Software

Product Affected

Part Number	Description	Old Revision	New Revision
SLS200PS20-01	SPIDER REMOTE IP KVM, PS2, RoHS	R29	T29
SLS200PS2X0-01	SPIDER REMOTE IP KVM, PS2, VGA, 58" EXTENDED CABLE, RoHS	P26	R26
SLS200USB0-01	SPIDER REMOTE IP KVM, USB, RoHS	R28	T28
SLS200USBX0-01	SPIDER REMOTE IP KVM, USB, VGA, 58" EXTENDED CABLE, RoHS	P26	R26
SLSLP400PS2-01	SPIDER DUO, LOCAL PORT, REMOTE IP KVM, PS2, 21.6" CABLE, ROHS	H20	J20
SLSLP400USB-01	SPIDER DUO, LOCAL PORT, REMOTE IP KVM, USB, 21.6" CABLE, ROHS	H21	J21

Description and Extent of Change

Lantronix is pleased to announce the release of SLS Application Firmware version 4.3.1. This new firmware includes bug fixes.

BUG FIXES:

SPID-46: Invalid CSR - Needs updating

SPID-47: " \ " key does not work in KVM window

For customers that would like to take advantage of the new capabilities immediately, the new firmware, associated release notes and upgrade instructions is available for download from our website, <http://www.lantronix.com/support/downloads>.

Effect of Change on Fit, Form, or Function

Functional changes as noted above.

Effective Date of Change

The change will go into effect for the listed products built from July 01, 2021 onwards.

If you have any questions, please contact your sales representative or Lantronix Technical Support at (800) 422-7044 or (949) 453-7198.