

PRODUCT CHANGE NOTICE

Dear Valued Lantronix Customer,

The purpose of this communication is to inform you of an upcoming change to the following product. This change is part of our effort and commitment to continuous improvement of our products and processes.

Change Type

Software

Product Affected

Part Number	Description	Old Revision	New Revision
MPR3002000-01	MATCHPORT AR DEVICE SERVER, AES, BULK, RoHS	E14	F14
MPR300200S-01	MATCHPORT AR DEVICE SERVER, AES, SAMPLE, RoHS	E16	F16

Description and Extent of Change

Lantronix is pleased to announce the release of MATCHPORT AR Firmware version 6.0.0.1R2. This new firmware includes bug fixes.

BUG FIXES:

- Modem Mode +++AT handling
- Memory leak while doing SSL handshake
- Root certificate in cert chain during SSL handshake then a CA check out performed.
- Multidrop/tristate topology not working on both Serial Port 1 and 2
- Update copyright information to 2021
- By default SNMP need to disabled

For customers that would like to take advantage of the new capabilities immediately, the new firmware, associated release notes and upgrade instructions is available for download from our website, <http://www.lantronix.com/support/downloads>.

Effect of Change on Fit, Form, or Function

Functional changes as noted above.

Effective Date of Change

The change will go into effect for the listed products built from July 05, 2021 onwards.

If you have any questions, please contact your sales representative or Lantronix Technical Support at (800) 422-7044 or (949) 453-7198.