

PRODUCT CHANGE NOTICE

Dear Valued Lantronix Customer,

The purpose of this communication is to inform you of an upcoming change to the following product. This change is part of our effort and commitment to continuous improvement of our products and processes.

Change Type

Software

Product Affected

Part Number	Description	Old Revision	New Revision
UD1100001-01	SINGLE PORT 10/100 DEVICE SERVER WITH US DOMESTIC POWER SUPPLY	K28	L28
UD1100002-01	SINGLE PORT 10/100 DEVICE SERVER WITH INTERNATIONAL POWER SUPPLY AND ADAPTERS	K28	L28
UD110000B-01	BOARD ONLY SINGLE PORT 10/100 DEVICE SERVER, ROHS	K21	L21
UD11000P0-01	POE UDS1100 SINGLE PORT 10/100 DEVICE SERVER, RoHS	G19	H19
UD1100IA2-01	IA, SINGLE PORT, 10/100 DEVICE SERVER, W/ INTERNATIONAL PSU AND ADAPTERS	D26	E26
UD1100NL2-01	SINGLE PORT NON-LABELED 10/100 DEVICE SERVER WITH INTERNATIONAL PSU & ADAPTERS, ROHS	J23	K23

Description and Extent of Change

Lantronix is pleased to announce the release of UDS 1100 Application Firmware version 7.0.0.3 and Web Manager version 2.0.0.13.

BUG FIXES:

- Change baudrate of Channel 1 on the fly via Telnet
- Cobos: update copyright information to 2021
- By default SNMP need to disabled across all cobos products

For customers that would like to take advantage of the new capabilities immediately, the new firmware, associated release notes and upgrade instructions is available for download from our website, <http://www.lantronix.com/support/downloads>.

Effect of Change on Fit, Form, or Function

Functional changes as noted above.

Effective Date of Change

This change will go into effect for the listed products built from **October 4, 2021** onwards.

If you have any questions, please contact your sales representative or Lantronix Technical Support at (800) 422-7044 or (949) 453-7198.

7535 Irvine Center Drive | Suite 100
Irvine, CA 92618 USA

 800.526.8766
 lantronix.com

FM-196 Rev. S