



Date: 11/22/2021

PCN:761

## PRODUCT CHANGE NOTICE

Dear Valued Lantronix Customer,

The purpose of this communication is to inform you of an upcoming change to the following product. This change is part of our effort and commitment to continuous improvement of our products and processes.

### **Change Type**

Software

### **Products Affected**

Part Number	Description	Old Revision	New Revision
SLB8824KIT-AP	SLB8824 BRANCH OFFICE MANAGER, 220VAC OUTPUT (8 SERIAL PORTS, 8 C13 OUTLETS, DUAL AC INLETS), AU AND CN POWER CORDS INCLUDED	J17	K17
SLB8824KIT-EU	SLB8824 BRANCH OFFICE MANAGER, 220VAC OUTPUT (8 SERIAL PORTS, 8 C13 OUTLETS, DUAL AC INLETS), EU AND UK POWER CORDS INCLUDED	J17	K17
SLB8824KIT-WW	SLB8824 BRANCH OFFICE MANAGER, 220VAC OUTPUT (8 SERIAL PORTS, 8 C13 OUTLETS, DUAL AC INLETS), AU, CN, EU, AND UK POWER CORDS INCLUDED	J17	K17
SLB882KIT-15P	SLB882 BRANCH OFFICE MANAGER 110VAC (8 SERIAL, 8 POWER, DUAL AC POWER INLETS), NEMA 5-15P (15A)	L20	M20
SLB882KIT-15P-G	SLB882 BRANCH OFFICE MANAGER 110VAC (8 SERIAL, 8 POWER, DUAL AC POWER INLETS), NEMA 5-15P (15A), TAA	D11	E11
SLB882KIT-20P	SLB882 BRANCH OFFICE MANAGER 110VAC (8 SERIAL, 8 POWER, DUAL AC POWER INLETS), NEMA 5-20P (20A)	L20	M20
SLB882KIT-20P-G	SLB882 BRANCH OFFICE MANAGER 110VAC (8 SERIAL, 8 POWER, DUAL AC POWER INLETS), NEMA 5-20P (20A), TAA	D11	E11

Lantronix is pleased to announce the release of new and improved SLB firmware 7.5.0.1RC7.

### **Description and Extent of Change**

The release includes new features and bug fixes including:

7535 Irvine Center Drive | Suite 100  
Irvine, CA 92618 USA

☎ 800.526.8766

🌐 [lantronix.com](http://lantronix.com)

FM-196 Rev. E

- **Modem White List**  
A list of allowed phone numbers can be used to control dial-in access to an internal modem or USB modem. The access list can be configured to either ignore or hang up phone numbers which are not on the access list.
- **Support for a serial connection on front USB port**  
The SLB now supports a USB serial device connected to the front U1 USB port. Users can login to the SLB and perform a "connect direct" to U1 to interact with the device.

**Reason for Change**

New features and expanded capabilities

For SLB customers who would like to take advantage of the above new capabilities, the firmware and associated release notes are now available for download from our website:

<https://www.lantronix.com/products/lantronix-slb/#docs-downloads>

More information about SLB Branch Office Manager is available on our website:

<https://www.lantronix.com/products/lantronix-slb>

**Effect of Change on Fit, Form, or Function**

Functional changes only as noted above.

**Effective Date of Change**

This change will go into effect for the listed products built from November 29, 2021 onwards.

If you have any questions, please contact your sales representative or Lantronix Technical Support at (800) 422-7044 or (949) 453-7198.