

PRODUCT CHANGE NOTICE

Dear Lantronix Customer,

The purpose of this communication is to inform you of an upcoming change to the following product. This change is part of our effort and commitment to continuous improvement of our products and processes.

Change Type

Software

Products Affected

Part Number	Description	Old Revision	New Revision
B41H00FB02	BOLERO41-PROMOTION-KIT	B11	C11
B41H00FS	BOLERO41, 60189, WORLWIDE - 2G BAND 5/8/3/2 - IP 68 ? GNSS - LI.ION BATTERY BACKUP - RS232 2 WIRES - 2 I/O - 1 WIRE INTERFACE - AVL SOFTWARE	B12	C12
B43H002S	TRACKER BOLERO43 - EMEA - LTE CATM1 BAND 20, 8, 3, 7- 2G FB BAND 8, 3 - IP 68 ? GNSS - LI.ION BATTERY BACKUP - RS232 2 WIRES - 2 I/O - 1 WIRE INTERFACE - AVL SOFTWARE	A12	B12
B45H00FB02	BOLERO45-PROMOTION-KIT	B11	C11
B45H00FS	BOLERO45, 60190, Worldwide - 3G band 5/8/2/1 - 2G FB - IP 68 ? GNSS - Li.Ion battery backup - RS232 2 wires - 2 I/O - 1 Wire interface - AVL Software	B11	C11

Description and Extent of Change

Lantronix is pleased to announce the availability of new firmware release **v3.16.0RC9** for BOLERO40 Series Products.

Improvements and bug fixes:

- Too many GPSTATE:Enable TLS security for WebUpdate events on AVL device while updating FW using HTTPS Web update link with invalid port no
- LUA functions dofile() and loadfile() are implemented
- BOLERO43 does not connect to Docomo
- Lua Abort reason as dynamic variable and event eLuaAborted
- Use MONPREF=100 as base for Verizon
- Added command to clear MQTT certificates (PFAL Command: TCP.MQTT.ClearCertificate)
- Increased size for PPP secrets (63 bytes)

Refer to the release notes for a complete list of features and bug fixes.

Effect of Change on Fit, Form, Function, Quality, or Reliability

Functional changes as noted on release notes.

For customers that would like to take advantage of the new capabilities immediately, the new firmware, associated release notes and upgrade instructions are available for download from our website, <http://www.lantronix.com/support/downloads>.

Effective Date of Change

This change will go into effect for the listed products built from **July 11, 2022** onwards.

If you have any questions, please contact your sales representative or Lantronix Technical Support at (800) 422-7044 or (949) 453-7198.