



Date: 08/28/2023

PCN: 878

PRODUCT CHANGE NOTICE

Dear Lantronix Customer,

The purpose of this communication is to inform you of an upcoming change to the following products. This change is part of our effort and commitment to continuous improvement of our products and processes.

Change Type

Firmware

Products Affected

Part Number	Description	Old Revision	New Revision
G528GP2FS	SECURITY PACK 5G Sub 6 GHZ LTE CAT13 FB IOT GATEWAY WORLD	A11	B11

Description and Extent of Change

Lantronix is pleased to announce the release of new and improved G528 application firmware version V2.1.0.0R30

The release includes bug fixes including :

- Getting CMS Error 500 on sending SMS in Verizon POD SIM.
- Unit keeps rebooting after some time.
- Not registering on C-bands n77, n78 and n79.
- Power loss not detected.
- SIM not auto registering till retries count get over (regression).
- POE timer configuration fields mentioned in UI not clear.

Reason for Change

New firmware release

Effect of Change on Fit, Form, Function

There is no impact to product fit, form, and function.

Effective Date of Change

This change will go into effect for the listed products built from **September 4, 2023** onwards.

If you have any questions, please contact your sales representative or contact Lantronix Technical Support by submitting a ticket to: <https://ltrxdev.atlassian.net/wiki/spaces/LTRXTS/overview>