



Transition Networks
10900 Red Circle Drive
Minnetonka, MN 55343
www.transition.com

SISPM1040-382-LRT Release Notes

Date: Oct.27, 2016

Version: 1.32

Overview

This release notes covers firmware version v1.32 for SISPM1040-382-LRT.

Release Changes and Enhancements

1. Fix provided for TLS v1.1 and v1.2 vulnerability for secure communications applications.

Known Limitations and Restrictions

1. EAP MD5 must be set as the default authentication method on any Radius server. This applies to Radius servers such as FreeRadius which may accept MD5 and have TLS as the default setting in EAP configuration.