



Carrier Ethernet Release Notes

Date: Mar 13, 2015

Version: 1.9.4

Overview

This release note covers the requirements, important notes, new features and changes, addressed issues and known limitations for the INDURA product family. Management of these products is available using Converge™ EMS, SNMP, Web or Command Line Interface (CLI) locally or via Telnet.

Requirements:

Firmware version 1.9.4 and these release notes apply to the following products:

- IND-3280-L
- IND-3284-L
- IND-3280-H
- IND-3284-H

New Features and Enhancements:

The following is a list of new features and enhancements for version 1.9.4

- Configurable Banner upon login for Message of the day (MOTD- available via CLI
- 2048 bit https certificate
- Collection of some Performance Monitoring stats on device
- Traps for EPS, ERPS
- Zero Touch Provisioning (ZTP)- ability to be auto discovered by a management system when connected into a network

Known Feature Limitations:

The following is a list of currently known issues for the INDURA.

- MEPs do not work over ports using link aggregation
- L2CP settings are in the CLI only and not Web interface

Related Documentation:

Please visit the specific product web page for detailed documentation

- Install Guide
- User Guide
- CLI Reference Guide

MIBs:

- tn-mibs-v1.9.4.zip file