



Transition Networks
10900 Red Circle Drive
Minnetonka, MN 55343
www.transition.com

SISGM1040-244-LRT Release Notes

Date: June 24, 2015

Version: 1.03

Kernel Version: 5.03.48

Overview

This release note covers the requirements, important notes, new features and changes, addressed issues and known limitations for the SISGM1040-244-LRT product.

Requirements:

Firmware version 1.03_k5.03.48 and these release notes apply to the following products:

- SISGM1040-244-LRT

New Features and Enhancements:

This release does not contain any feature enhancements.

Bug Fixes:

- When the device receives a large number of UDP packets (500MB and up) the device CPU hangs.
- When the Username and Password are modified through the CLI commands, the Username and Password for Web UI access is not updated properly.
- Cannot access the device through the Web UI after the Username and Password are modified and saved.