

Date: October 17, 2007

Product Discontinuation Reminder

Dear Valued Lantronix Customer,

As a reminder, Lantronix has discontinued the SCS820, SCS1620, SCS3205 and SCS4805 Console Servers and related accessories.

The deadline for placing final purchase orders was September 29, 2006, with shipments scheduled no later than November 30, 2006. This was extended due to customer demand, but the date for final shipments has now passed.* The last day of support for these products is February 29, 2008.

In addition, the extended services for these products have also been discontinued. Please see the attached list for service part nos. that will no longer be available for purchase after October 31, 2007. Lantronix will continue to support all previously purchased extended services for these products through the duration of each individual contract.

SUGGESTED REPLACEMENT: SECURELINX™ SLC CONSOLE MANAGER

As a replacement for the SCSxx05 and SCSxx20 products, please consider the award winning SecureLinx™ SLC Console Manager. Available in 8, 16, 32 and 48 port configurations, with single-AC, dual-AC and dual-DC power supply options, SLC offers an advanced feature set, high availability, expandability via PC card, extensive reporting and diagnostics, and it's easy to use. SLC is also recognized by Network Computing as an Editor's Choice. For more information, please visit our web site (<http://www.lantronix.com/slc>)

If you have any questions, please contact your sales representative or Lantronix Customer Support at (866) 649-0721 or (949) 453-3990 x342.

LANTRONIX®
Product Marketing

*Note: If you're interested in purchasing spare product, Lantronix still has limited stock available. Purchase orders will be accepted while supplies last.

Date: October 17, 2007

Product Discontinuation Announcement

Hardware Part #	Service Part #
500.xxx.0820x	SC08207EW-0A
500.xxx.0820x	SC08207EW-0B
500.xxx.0820x	SC08207EW-0C
500.xxx.0820x	SC08207EW-0D
500.xxx.0820x	SC0820724-0A
500.xxx.0820x	SC0820724-0B
500.xxx.0820x	SC0820724-0C
500.xxx.0820x	SC0820724-0D
500.xxx.0820x	SC08207AR-0A
500.xxx.0820x	SC08207AR-0B
500.xxx.0820x	SC08207AR-0C
500.xxx.0820x	SC08207AR-0D
500.xxx.1620x	SC16207EW-0A
500.xxx.1620x	SC16207EW-0B
500.xxx.1620x	SC16207EW-0C
500.xxx.1620x	SC16207EW-0D
500.xxx.1620x	SC1620724-0A
500.xxx.1620x	SC1620724-0B
500.xxx.1620x	SC1620724-0C
500.xxx.1620x	SC1620724-0D
500.xxx.1620x	SC16207AR-0A
500.xxx.1620x	SC16207AR-0B
500.xxx.1620x	SC16207AR-0C
500.xxx.1620x	SC16207AR-0D
SCS3205U-01	SC32057EW-0A
SCS3205U-01	SC32057EW-0B
SCS3205U-01	SC32057EW-0C
SCS3205U-01	SC32057EW-0D
SCS3205U-01	SC3205724-0A
SCS3205U-01	SC3205724-0B

Hardware Part #	Service Part #
SCS3205U-01	SC3205724-0C
SCS3205U-01	SC3205724-0D
SCS3205U-01	SC32057AR-0A
SCS3205U-01	SC32057AR-0B
SCS3205U-01	SC32057AR-0C
SCS3205U-01	SC32057AR-0D
SCS4805U-01	SC48057EW-0A
SCS4805U-01	SC48057EW-0B
SCS4805U-01	SC48057EW-0C
SCS4805U-01	SC48057EW-0D
SCS4805U-01	SC4805724-0A
SCS4805U-01	SC4805724-0B
SCS4805U-01	SC4805724-0C
SCS4805U-01	SC4805724-0D
SCS4805U-01	SC48057AR-0A
SCS4805U-01	SC48057AR-0B
SCS4805U-01	SC48057AR-0C
SCS4805U-01	SC48057AR-0D
500.000.0820A	SC08207EW-RA
500.000.0820A	SC08207EW-RB
500.000.0820A	SC08207EW-RC
500.000.1620A	SC16207EW-RA
500.000.1620A	SC16207EW-RB
500.000.1620A	SC16207EW-RC
SCS3205U-01	SC32057EW-RA
SCS3205U-01	SC32057EW-RB
SCS3205U-01	SC32057EW-RC
SCS4805U-01	SC48057EW-RA
SCS4805U-01	SC48057EW-RB
SCS4805U-01	SC48057EW-RC