

Transition Networks 10900 Red Circle Drive Minnetonka, MN 55343 www.transition.com

SISPM1040-384-LRT-B Release Notes

Date: Apr.7, 2017 Version: 1.30_k10.08

Overview

This release notes covers firmware version v1.30_k10.08 for SISPM1040-384-LRT-B.

Release Changes and Enhancements

[Fixed]

- 1. Port Alias description did not save in restore config
- 2. No help file in Port Alias page view
- 3. No logout icon in Web GUI
- 4. Remove ALL EVC field

Known Limitations and Restrictions

N/A