

# ION C2110 Product Notice Date: February 17, 2012

## Overview

This product notice involves a PCB labeling error on early production units of the ION C2110 media converter.

## **Affected Products:**

This notice only applies to ION C2110-10xx cards with a seven digit serial number that does not begin with the number nine (9).

#### Issue:

The hardware/software jumper

• Board positions labeled J5 and J6 are reversed.

## **Resolution:**

• This PCB labeling issue has been corrected on current production units.

### **Known Limitation:**

• No functional limitations, the hardware/software jumper works correctly.

## **Related Documentation:**

• ION C2110 Install Guide (33415)