

15353 Barranca Parkway Irvine I CA 92618 USA Tel: 949-453-3990 Fax: 949-453-7170 www.lantronix.com

PCN No.: PCN-019

October 12, 2004

Product Change Notice

Dear Valued Lantronix Customer,

The purpose of this document is to notify you of a firmware change to the SCS820B, SCS1620B, SCS3205 and SCS4805 Secure Console Servers.

Firmware version 4.4.1 will ship on the following products at the end of October 2004:

Model Number	Part Number
SCS820B (AC)	500.000.0820B
SCS820B (DC)	500.048.0820B
SCS1620B (AC)	500.000.1620B
SCS1620B (DC)	500.048.1620B
SCS3205	SCS3205U-01
SCS4805	SCS4805U-01

This version replaces the previous version, 4.3. It includes fixes for known issues in version 4.3, including, but not limited to the following:

- Updated LDAP authentication for improved compatibility with MS Active Directory
- OpenSSH (2.9.9p2) has been patched to account for all known security issues as of 6/15/2004
- Latest ltxloggrd (1.25) fixes all known logging to file and email notification issues

An upgrade patch and release notes will be posted on the Lantronix web site in the next few weeks at: <u>http://www.lantronix.com/support/downloads.html</u>*.

For more information, contact Lantronix Customer Support at (866) 649-0721 or (949) 453-3990 x342.

* If you are currently running v4.3, an update to v4.4 will have to be completed first.

LANTRONIX[®] Product Marketing