

Date: 07/10/2014

PCN No.: 243

PRODUCT CHANGE NOTICE

Dear Valued Lantronix Customer,

SLC Secure Console Manager Firmware Release

Lantronix is pleased to announce the release of new and improved firmware version 6.1.0.0 for the Lantronix SLC Secure Console Manager. The new firmware, now available at the Lantronix website, offers several new improvements, including:

- Support for controlling a ServerTech PDU connected to a device port
- Enhanced SSH Key support
- Improved web support for custom menus
- Support for custom groups and LDAP groups
- Improved support for RADIUS FilterID
- Improved IP filter support
- Secondary SNMP NMS
- SSH login timeout
- SSL improved

For more information about the new firmware and upgrade instructions, please visit:
http://ltxfaq.custhelp.com/app/answers/detail/a_id/1001.

Because of the new firmware release, we are making changes to the following products.

Product(s) Affected

Part Number	Description	Current Revision	New Revision (F/W v6.1.0.0)
SLC00812N-G3	8-Port, Single AC Power Supply, Secure Console Manager, ROHS, TAA	A14	B15
SLC00822N-G3	8-Port, Dual AC Power Supply, Secure Console Manager, ROHS, TAA	B21	C22
SLC00824N-G3	8-Port, Dual DC Power Supply, Secure Console Manager, ROHS, TAA	A14	B15
SLC01612N-G3	16-Port, Single AC Power Supply, Secure Console Manager, ROHS, TAA	B20	C21
SLC01622N-G3	16-Port, Dual AC Power Supply, Secure Console Manager, ROHS, TAA	B21	C22
SLC01624N-G3	16-Port, Dual DC Power Supply, Secure Console Manager, ROHS, TAA	A14	B15

Part Number	Description	Current Revision	New Revision (F/W v6.1.0.0)
SLC03212N-G3	32-Port, Single AC Power Supply, Secure Console Manager, ROHS, TAA	B17	C18
SLC03222N-G3	32-Port, Dual AC Power Supply, Secure Console Manager, ROHS, TAA	B21	C22
SLC03224N-G3	32-Port, Dual DC Power Supply, Secure Console Manager, ROHS, TAA	A14	B15
SLC04812N-G3	48-Port, Single AC Power Supply, Secure Console Manager, ROHS, TAA	B20	C21
SLC04822N-G3	48-Port, Dual AC Power Supply, Secure Console Manager, ROHS, TAA	C22	D23
SLC04824N-G3	48-Port, Dual DC Power Supply, Secure Console Manager, ROHS, TAA	A14	B15

Change Type

- New Firmware Revision
- Box Content Change: Removed CD-ROM

Description and Extent of Change

- Product will now have the SLC Console Manager Firmware v6.1.0.0
- The CD-ROM is no longer included in the box. CD-ROM contents, which may include software, documentation, and/or utilities, can be downloaded from the Lantronix website.
<http://www.lantronix.com/downloads>

Effect of Change on Fit, Form, Function, Quality, or Reliability

Change is limited to product functionality. Refer to the release notes for details.

Effective Date of Change

Shipment of product with the above changes will commence by July 15, 2014.

If you have any questions, please contact your sales representative or Lantronix Customer Support at (866) 649-0721