

Date: 7/30/15

PCN No.: 322

PRODUCT CHANGE NOTICE

Dear Valued Lantronix Customer,

This is to inform you that a change has been made to the following products.

Change Type

Firmware

Products Affected

Part Number	Description	Old Revision	New Revision
EDS008PS-02	DESKTOP SECURE DEVICE SERVER, 8 PORT, ROHS	D18	E19
EDS016PS-02	DESKTOP SECURE DEVICE SERVER, EDS, 16-PORT, ROHS	D19	E20

Description and Extent of Change

- The boot loader (residing in the pre-programmed flash) was updated to improve manufacturing yields and reliability.
 - This boot loader update resolves the occasional issue of unit continuously trying to access a non-existent UART on expansion bus 1 during boot up sequence.
- Application firmware is unchanged and remains at 5.2.0.3R1.
- Updated Release Notes and boot loader file will be available for download from our website: <http://www.lantronix.com/support/downloads.html> on Thursday, 7/30/2015.

Effect of Change on Fit, Form, Function, Quality, or Reliability

Change is limited to product functionality.

Effective Date of Change

Affected products with updated boot loader begin shipping from the factory in July 2015.

If you have any questions, please contact your sales representative or Lantronix Customer Support at (866) 649-0721 or (949) 453-3990 x342.