

## PRODUCT CHANGE NOTICE

Dear Valued Lantronix Customer,

The purpose of this communication is to inform you of an upcoming change to the following product. This change is part of our effort and commitment to continuous improvement of our products and processes.

### **Change Type**

Software

### **Product Affected**

Part Number	Description	Old Revision	New Revision
XP1001000-05R	XPORT XE, EXTENDED TEMPERATURE, BULK WITH 00-80-A3-XX-XX-XX MAC ADDRESS, ROHS	C12	D12
XP1001000-05R J	XPORT XE, EXTENDED TEMPERATURE, BULK WITH 00-80-A3-XX-XX-XX MAC ADDRESS - JAPAN ONLY, ROHS	C12	D12
XP1001000-05R-AP	XPORT 05R, BULK, ASIA PAC, ROHS	C12	D12
XP1001000M-05R	XPORT XE ROHS EXTENDED TEMP MODBUS BULK	C12	D12
XP100100G-05R	XPORT X, EXTENDED TEMPERATURE, DEVICE SERVER, BULK, TAA, ROHS	B11	C11
XP1002000-05R	XPORT, EXTENDED TEMPERATURE, ENCRYPTION, BULK WITH 00-80-A3-XX-XX-XX MAC ADDRESS, ROHS	C12	D12
XP1002000-05R J	XPORT 05, W/AES, JAPAN ONLY	C12	D12
XP100200G-05R	XPORT SE, EXTENDED TEMPERATURE, DEVICE SERVER, AES ENCRYPTION, BULK, TAA, ROHS	B11	C11
XP100200S-05R	XPORT, EXTENDED TEMPERATURE, ENCRYPTION, SAMPLE WITH 00-80-A3-XX-XX-XX MAC ADDRESS, ROHS	C13	D13
XP100200S-05R J	XPORT, EXTENDED TEMPERATURE, ENCRYPTION WITH 00-80-A3-XX-XX-XX MAC ADDRESS, SAMPLE JAPAN ONLY, ROHS	C13	D13

### **Description and Extent of Change**

Lantronix is pleased to announce the release of XPORT Application Firmware version 7.0.0.3 and Web Manager version 2.0.0.13.

BUG FIXES:

- Change baudrate of Channel 1 on the fly via Telnet
- Cobos: update copyright information to 2021
- By default SNMP need to disabled across all cobos products

For customers that would like to take advantage of the new capabilities immediately, the new firmware, associated release notes and upgrade instructions is available for download from our website, <http://www.lantronix.com/support/downloads>.

### **Effect of Change on Fit, Form, or Function**

Functional changes as noted above.

**Effective Date of Change**

This change will go into effect for the listed products built from **October 4, 2021** onwards.

If you have any questions, please contact your sales representative or Lantronix Technical Support at (800) 422-7044 or (949) 453-7198.