

PRODUCT CHANGE NOTICE

Dear Lantronix Customer,

The purpose of this communication is to inform you of an upcoming change to the following product. This change is part of our effort and commitment to continuous improvement of our products and processes.

Change Type

Software

Products Affected

Part Number	Description	Old Revision	New Revision
M111F00FB22	M111F00FS MODEM WITH ANTENNA A17C1, CABLE KS990, POWER CABLE KDC42, DIN CLIP BR350 (HSN CODE: 85176230)	A12	B12
M111F00FS	MODEM M111 - WORLDWIDE - 2G QUAD BAND - RS-232 & USB PORTS - 2 I/OS - MPACK	A12	B12
M114F000S	MODEM M114 AT&T, TMOBILE, SPRINT - NORTH AMERICA - LTE CAT. 1 BAND 12, 5, 4, 2 - 3G FB BAND 5, 2 - RS-232 & USB PORTS - 2 I/OS - MPACK	B12	C12
M114F001S	MODEM M114 US / VERIZON - LTE CAT. 1 BAND 13/4 - NO FALL BACK - RS-232 & USB PORTS - 2 I/OS	B12	C12
M114F002B23	M114F002S MODEM WITH ANTENNA A32M0, CABLE KS990, POWER CABLE KDC42, DIN CLIP BR350 (HSN CODE: 85176230)	B12	C12
M114F002S	MODEM M114 EMEA - LTE CAT. 1 BAND 20, 3, 7 - 2G FB BAND 8, 3 - RS-232 & USB PORTS - 2 I/OS - MPACK	B12	C12
M114F003B23	M114F003S MODEM WITH ANTENNA A32M0, CABLE KS990, POWER CABLE KDC42, DIN CLIP BR350 (HSN CODE: 85176230)	B12	C12
M114F003S	MODEM M114 ASIA PACIFIC - LTE CAT. 1 BAND 28, 8, 3 - 3G FB BAND 1 - RS-232 & USB PORTS - 2 I/OS - MPACK	B12	C12
M114F005S	MODEM M114 DOCOMO - JAPAN - LTE CAT. 1 BAND 19, 1 - NO FALL BACK - RS-232 & USB PORTS - 2 I/OS - MPACK	B12	C12
M115F00FS	MODEM M115 - WORLDWIDE - 3G BAND 5, 8, 3, 1 - 2G FB BAND 5, 8, 3, 2 - RS-232 & USB PORTS - 2 I/OS - MPACK	A12	B12

Description and Extent of Change

Lantronix is pleased to announce the availability of new firmware release **v2.8.0.0** for M-Series Modem Products.

New Features:

- o Support for LARA-R204-02B
- o Support for AUOPT=4 command option
- o Support for LARA-R281 (M114F004S)

- o Command to Enable/Disable +UUPSDA URC (AT#PSDURC).
- o Command to Enable/Disable USB Switching for Firmware Upgrade (AT#USBMODE).

Refer to the release notes for a complete list of features and bug fixes.

Effect of Change on Fit, Form, Function, Quality, or Reliability

Functional changes as noted on release notes.

For customers that would like to take advantage of the new capabilities immediately, the new firmware, associated release notes and upgrade instructions are available for download from our website, <http://www.lantronix.com/support/downloads>.

Effective Date of Change

This change will go into effect for the listed products built from **January 13, 2022** onwards.

If you have any questions, please contact your sales representative or Lantronix Technical Support at (800) 422-7044 or (949) 453-7198.