

Date: 08/15/2023 PCN: 875

PRODUCT CHANGE NOTICE

Dear Lantronix Customer,

The purpose of this communication is to inform you of an upcoming change to the following product. This change is part of our effort and commitment to continuous improvement of our products and processes.

Change Type

Software

Products Affected

Part Number	Description	Old	New
		Revision	Revision
B43H207S	BOLERO43 WATERPROOF (IP68-RATED) VEHICLE TRACKER FOR JAPAN	A11	B11

Description and Extent of Change

Lantronix is pleased to announce the availability of new firmware release v3.19.0rc4 for BOLERO43 product.

Improvements and bug fixes:

- Implemented FOTA procedure for TOBY devices, see gsm_fota.cxx (#AVL3-410)
- Enable batmode DEVICE.BAT.MODE=always, see device.cxx (#AVL3-426)
- GSM.StartFOTA,"<resource>"[,<port>]: Set the FOTA resource and start update. The update resource is encoded as ftp://[user:pwd@]ftp.server.com/path/file.zip
- GSM.StopFOTA: Stop a pending update procedure

Refer to the release notes for a complete list of features and bug fixes.

Effect of Change on Fit, Form, Function, Quality, or Reliability

Functional changes as noted on release notes.

For customers that would like to take advantage of the new capabilities immediately, the new firmware, associated release notes and upgrade instructions are available for download from our website, http://www.lantronix.com/support/downloads.

Effective Date of Change

This change will go into effect for the listed products built from **September 04, 2023** onwards.

If you have any questions, please contact your sales representative or Lantronix Technical Support at (800) 422-7044 or (949) 453-7198.