



IONPS Release Notes

Date: May 30, 2011

Version: 1.1.0

Overview

This release note covers the requirements, important notes, new features and changes, addressed issues, and known limitations for the IONPS-A and the IONPS-D power supplies.

Management of the IONPS requires the use of an IONMM management module installed in the ION219 chassis. Management information is available using a web browser or via Command Line Interface (CLI) via the local USB port or telnet of the IONMM.

Requirements:

Firmware version 1.1.0 and these release notes apply to the following products:

- IONPS-A
- IONPS-D

New Features and Enhancements:

The following list is new features and enhancements for version 1.1.0 of the IONPS-A and IONPS-D products.

- The indication of a power supply failure has been enhanced to make it easier for users to receive this information.
- The Back-up and Restore functions for the IONPS has been improved.

Known Feature Limitation:

The following list is currently known issues for the IONPS products.

- Transition Networks recommends the use of Microsoft Internet Explorer for web-based management.
- If a fan on the power supply fails, users may not receive the correct indication of the fans operating status.

Related Documentation:

- ION219-A User Guide (33412)
- IONPS-A User Guide (33423)
- IONPS-D User Guide (33424)